

Inventory Report



TENANT NAME



TENANCY TYPE

Multiple

REPORT CONFIRMED BY



PROPERTY VISIT DATE

29/03/2026

PREPARED ON BEHALF OF



 [View Photo Gallery](#)

This report contains



Inventory details: Record of meter readings (where accessible). Record of fire and smoke alarm compliance.



Detailed descriptions and schedule of condition and cleanliness for all fixtures and fittings.



Disclaimer and check-out guidance details.

Property Information

This is a detached property with both front and back gardens.

Report Information

Smoke and carbon monoxide alarms present throughout the property.

Glossary of Terms

For guidance, please find a glossary of terms used within this report:

Condition

Very Poor: Extensively damaged/faulty. Examples: large stains; upholstery torn; very dirty.

Poor: Extensive signs of wear and tear. Examples: stains/marks/tears/chips.

Fair: Signs of age. Examples: frayed; small light stains/marks; discolouration.

Good: Signs of slight wear. Examples: generally lightly worn.

New Item: Still in wrapper or with new tags/labels attached. Recently purchased, installed or decorated.

Cleanliness

Very Poor: Not cleaned. Requires cleaning to a good or excellent standard.

Poor: Item dusty or dirty. Requires further cleaning to either good or excellent standard.

Fair: Evidence of some cleaning, but signs of dust or marks.

Good: Item cleaned and free of loose dirt.

Excellent: Item immaculate, sparkling and dust free.

Photo Terms

Captured (external device)

The date provided by the image file itself, usually set by the device that captured it.

Captured (via App)

The date a photo was taken within the platform mobile App. This is a more reliable source than the above.

Captured (certified by inspector)

The date a photo was taken according to the inspector (defaulting to the inspection date).

Added

The date on which the photo was added to the platform.

Status Icons



Disagreed by tenant



Repair



Beyond fair wear and tear



Replace



Missing

Health & Safety Alarm Compliance Checks



Health & Safety Alarm Compliance Checks

- | | |
|-----|--|
| YES | Do all floors have smoke/heat alarms present? |
| YES | Do all smoke/heat alarms have working test buttons? |
| NO | Are any areas requiring a smoke/heat alarm missing an installed unit? |
| NO | Are any smoke/heat alarms approaching the last 3 months of their life cycle? |
| YES | Are carbon monoxide alarms present in rooms with a fuel burning source (excluding gas cooking appliances) or flue? |
| YES | Do all carbon monoxide alarms have working test buttons? |
| NO | Are any areas requiring a carbon monoxide alarm missing an installed unit? |
| NO | Are any carbon monoxide alarms approaching the last 3-months of their life cycle? |




Health & Safety Alarm Compliance Notes


Smoke and carbon monoxide alarms present throughout the property.




Health & Safety Alarm Compliance Photos



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	30/03/2026



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	30/03/2026



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	30/03/2026

Compliance Items					
Room	Item	Description	Date Tested	Expiry Date	Photos
<u>Entrance/Hallway</u>	<u>Smoke Alarm</u>	Ceiling mounted alarm. Test function working. Note to tenant: Please test periodically. 1 fire alarm present on the ground floor. 1 carbon monoxide alarm present on the ground floor. 1 fire alarm present on the first floor.	29/03/2026	N/A	 3 photos



Schedule of Cleanliness and Condition

General Overview

Room/Space	Description	Condition	Cleanliness	Photos
<u>Entrance/Hallway</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Entrance in good condition. Door in excellent condition with minimal to no wear and tear marks present. Walls in excellent condition with no wear and tear marks present. Flooring in excellent condition with a few wear and tear marks present.	● Good	● Excellent	15 photos
<u>Living Room/Lounge</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Living room in excellent condition. Walls in excellent condition with no wear and tear marks present. Flooring in excellent condition with minimal wear and tear marks which have been noted down. Sofas and TV stand may be provided to tenant but still up for discussion. Lights all working.	● Good	● Excellent	15 photos
<u>Dining Room</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Dining room in excellent condition. Doors in excellent condition with some minimal wear and tear marks which have been noted down. Walls in excellent condition with no wear and tear marks which have been noted down. Flooring in excellent condition with some minimal wear and tear marks which have been noted down. Dining table and storage unit may be given to the tenant. Picture provided in dining room area. Lights all working.	● Good	● Excellent	15 photos
<u>Bathroom</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bathroom in excellent condition. Door in excellent condition with no wear and tear marks present. Flooring tiles in excellent condition with no wear and tear marks. Toilet in excellent condition. Sink tap in good condition but some limescale present which has been noted down. Shower head tap in good condition with no limescale visible. Lights all working.	● Good	● Excellent	13 photos

Room/Space	Description	Condition	Cleanliness	Photos
<u>Kitchen</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Kitchen in excellent condition. Walls in excellent condition with no wear and tear marks present. Flooring in excellent condition with no wear and tear marks present. Cupboards in good condition with some little makes present which have been noted down. Lights all working.	● Good	● Excellent	📷 14 photos
<u>Attached Dining Room</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Attached dining room in excellent condition. Walls in excellent condition with no wear and tear marks present. Flooring in excellent condition with no marks visible. Storage / Utility room in good condition however some marks present which have been noted down in the pictures. Lights all working.	● Good	● Excellent	📷 13 photos
<u>Stairway/Landing</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks present. Railing in excellent condition with no wear and tear marks present. Lights all working.	● Good	● Excellent	📷 14 photos
<u>Bedroom</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bedroom in excellent condition. Door in excellent condition with no wear and tear marks present. Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks visible. Radiator in excellent condition with no wear and tear marks present. Lights all working.	● Good	● Excellent	📷 12 photos
<u>Bedroom</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bedroom in excellent condition. Door in excellent condition with no wear and tear marks. Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks visible. Attached storage units in good condition with some marks visible which have been noted down. Lights all working.	● Good	● Excellent	📷 15 photos
<u>Utility/Laundry Room</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Storage / Utility room in good condition however some marks present which have been noted down in the pictures.	● Good	● Excellent	📷 9 photos

Room/Space	Description	Condition	Cleanliness	Photos
<u>Bathroom</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bathroom in excellent condition. Door in excellent condition with no wear and tear marks present. Flooring tiles in excellent condition with no wear and tear marks. Toilet in excellent condition. Sink tap in excellent condition with no limescale present. Shower head tap in good condition with no limescale visible. Lights all working.	● Good	● Excellent	📷 15 photos
<u>Bedroom</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bedroom in excellent condition. Door in excellent condition with no wear and tear marks. Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks visible. Attached storage units in good condition with some wear and tear marks visible which have been noted down. Lights all working.	● Good	● Excellent	📷 13 photos
<u>Bedroom</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bedroom in excellent condition. Door in excellent condition with no wear and tear marks. Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks visible. Attached storage units in good condition with some wear and tear marks visible which have been noted down. Lights all working.	● Good	● Excellent	📷 15 photos
<u>Ensuite</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bathroom in excellent condition. Door in excellent condition with no wear and tear marks present. Flooring tiles in excellent condition with no wear and tear marks. Toilet in excellent condition. Sink tap in good condition but some limescale present which has been noted down. Shower head tap in good condition with some little limescale visible. Lights all working.	● Good	● Excellent	📷 15 photos
<u>Utility/Laundry Room</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Storage / Utility room in good condition however some marks present which have been noted down in the pictures.	● Good	● Excellent	📷 8 photos
<u>Front Garden</u>	Good seasonal order. Grass 1 inch long. Weed free Fair seasonal order. Fencing appears secure. Refer to overview photos for items present, paved areas and grass length (if/where applicable). Front garden in good condition. Grass in good condition and a paved area present as well.	● Good	● Good	📷 3 photos

Room/Space	Description	Condition	Cleanliness	Photos
<u>Car Parking Space</u>	Gravel area. Paved area. Block paved area. Clear allocated markings. Free of oil/paint stains Refer to photos for allocated line markings and condition (if/where applicable). Clearly allocated parking areas present. All parking spaces free of oil stains.	● Good	● Good	 3 photos
<u>Keys</u>	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). 1 front door key provided to the tenants. 1 back door key provided to the tenants. 1 garage key provided to the tenants.	● Good	● Excellent	 2 photos



Utility Details

General Utility Notes

Electricity - 21612.7 kWh

General Utility Photos



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	30/03/2026



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	30/03/2026



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	30/03/2026



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	30/03/2026



Room Details


The small thumbnail images in this section can be used as a reference point. **Larger copies** of these images can be found in the **'Room Image Library'** section towards the end of this report.

1 Entrance/Hallway				
Item	Description	Condition	Cleanliness	Photos
1.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Entrance in good condition. Door in excellent condition with minimal to no wear and tear marks present. Walls in excellent condition with no wear and tear marks present. Flooring in excellent condition with a few wear and tear marks present.	● Good	● Excellent	15 photos
1.2 Smoke Alarm	Ceiling mounted alarm. Test function working. Note to tenant: Please test periodically. 1 fire alarm present on the ground floor. 1 carbon monoxide alarm present on the ground floor. 1 fire alarm present on the first floor.	● Good	● Excellent	3 photos




Entrance/Hallway Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.9




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.10




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.11



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.12



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.13




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.14




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.1.15


Smoke Alarm



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.2.1



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.2.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	1.2.3

2 Living Room/Lounge


Item	Description	Condition	Cleanliness	Photos
2.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Living room in excellent condition. Walls in excellent condition with no wear and tear marks present. Flooring in excellent condition with minimal wear and tear marks which have been noted down. Sofas and TV stand may be provided to tenant but still up for discussion. Lights all working.	● Good	● Excellent	📷 15 photos

📷 Living Room/Lounge Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.9




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.10




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.11




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.12



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.13



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.14




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	2.1.15

3 Dining Room


Item	Description	Condition	Cleanliness	Photos
3.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Dining room in excellent condition. Doors in excellent condition with some minimal wear and tear marks which have been noted down. Walls in excellent condition with no wear and tear marks which have been noted down. Flooring in excellent condition with some minimal wear and tear marks which have been noted down. Dining table and storage unit may be given to the tenant. Picture provided in dining room area. Lights all working.	● Good	● Excellent	15 photos

Dining Room Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.9



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.10




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.11



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.12



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.13



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.14




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	3.1.15

4 Bathroom


Item	Description	Condition	Cleanliness	Photos
4.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bathroom in excellent condition. Door in excellent condition with no wear and tear marks present. Flooring tiles in excellent condition with no wear and tear marks. Toilet in excellent condition. Sink tap in good condition but some limescale present which has been noted down. Shower head tap in good condition with no limescale visible. Lights all working.	● Good	● Excellent	📷 13 photos

📷 Bathroom Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.5



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.9




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.10



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.11



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.12




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	4.1.13

5 Kitchen


Item	Description	Condition	Cleanliness	Photos
5.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Kitchen in excellent condition. Walls in excellent condition with no wear and tear marks present. Flooring in excellent condition with no wear and tear marks present. Cupboards in good condition with some little makes present which have been noted down. Lights all working.	● Good	● Excellent	📷 14 photos

📷 Kitchen Photos

General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.3



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.4



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.5



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.6



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.7



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.8



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.9




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.10




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.11



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.12



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.13




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	5.1.14

6 Attached Dining Room


Item	Description	Condition	Cleanliness	Photos
6.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Attached dining room in excellent condition. Walls in excellent condition with no wear and tear marks present. Flooring in excellent condition with no marks visible. Storage / Utility room in good condition however some marks present which have been noted down in the pictures. Lights all working.	● Good	● Excellent	📷 13 photos

📷 Attached Dining Room Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.3



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.5



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.8



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.9




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.10



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.11



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.12




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	6.1.13

7 Stairway/Landing


Item	Description	Condition	Cleanliness	Photos
7.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks present. Railing in excellent condition with no wear and tear marks present. Lights all working.	● Good	● Excellent	📷 14 photos

📷 Stairway/Landing Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.9




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.10




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.11



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.12



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.13




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	7.1.14

8 Bedroom


Item	Description	Condition	Cleanliness	Photos
8.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bedroom in excellent condition. Door in excellent condition with no wear and tear marks present. Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks visible. Radiator in excellent condition with no wear and tear marks present. Lights all working.	● Good	● Excellent	 12 photos

Bedroom Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.8



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.9



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.10



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.11



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	8.1.12

9 Bedroom


Item	Description	Condition	Cleanliness	Photos
9.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bedroom in excellent condition. Door in excellent condition with no wear and tear marks. Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks visible. Attached storage units in good condition with some marks visible which have been noted down. Lights all working.	● Good	● Excellent	15 photos

Bedroom Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.9



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.10




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.11




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.12



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.13



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.14



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	9.1.15

10 Utility/Laundry Room


Item	Description	Condition	Cleanliness	Photos
10.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Storage / Utility room in good condition however some marks present which have been noted down in the pictures.	● Good	● Excellent	9 photos

Utility/Laundry Room Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	10.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	10.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	10.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	10.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	10.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	10.1.6



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	10.1.7



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	10.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	10.1.9

11 Bathroom


Item	Description	Condition	Cleanliness	Photos
11.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bathroom in excellent condition. Door in excellent condition with no wear and tear marks present. Flooring tiles in excellent condition with no wear and tear marks. Toilet in excellent condition. Sink tap in excellent condition with no limescale present. Shower head tap in good condition with no limescale visible. Lights all working.	● Good	● Excellent	📷 15 photos

📷 Bathroom Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.9



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.10



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.11




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.12



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.13



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.14




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	11.1.15

12 Bedroom


Item	Description	Condition	Cleanliness	Photos
12.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bedroom in excellent condition. Door in excellent condition with no wear and tear marks. Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks visible. Attached storage units in good condition with some wear and tear marks visible which have been noted down. Lights all working.	● Good	● Excellent	 13 photos

Bedroom Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.5



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.6



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.8



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.9



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.10



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.11



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.12




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	12.1.13

13 Bedroom


Item	Description	Condition	Cleanliness	Photos
13.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bedroom in excellent condition. Door in excellent condition with no wear and tear marks. Walls in excellent condition with no wear and tear marks present. Carpet in excellent condition with no marks visible. Attached storage units in good condition with some wear and tear marks visible which have been noted down. Lights all working.	● Good	● Excellent	15 photos

Bedroom Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.6



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.9



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.10




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.11




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.12



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.13



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.14




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	13.1.15

14 Ensuite


Item	Description	Condition	Cleanliness	Photos
14.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Bathroom in excellent condition. Door in excellent condition with no wear and tear marks present. Flooring tiles in excellent condition with no wear and tear marks. Toilet in excellent condition. Sink tap in good condition but some limescale present which has been noted down. Shower head tap in good condition with some little limescale visible. Lights all working.	● Good	● Excellent	📷 15 photos

📷 Ensuite Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.5




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.6




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.7




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.8




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.9




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.10




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.11



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.12



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.13



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.14




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	14.1.15

15 Utility/Laundry Room


Item	Description	Condition	Cleanliness	Photos
15.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). Storage / Utility room in good condition however some marks present which have been noted down in the pictures.	● Good	● Excellent	📷 8 photos

📷 Utility/Laundry Room Photos


General Overview




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	15.1.1




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	15.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	15.1.3




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	15.1.4




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	15.1.5



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	15.1.6



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	15.1.7





Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	15.1.8

16 Front Garden

Item	Description	Condition	Cleanliness	Photos
16.1 Overview (External)	Good seasonal order. Grass 1 inch long. Weed free Fair seasonal order. Fencing appears secure. Refer to overview photos for items present, paved areas and grass length (if/where applicable). Front garden in good condition. Grass in good condition and a paved area present as well.	● Good	● Good	📷 3 photos

📷 Front Garden Photos

Overview (External)



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	16.1.1

Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	16.1.2

Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	16.1.3

17 Car Parking Space				
Item	Description	Condition	Cleanliness	Photos
17.1 Overview (Parking Space)	Gravel area. Paved area. Block paved area. Clear allocated markings. Free of oil/paint stains Refer to photos for allocated line markings and condition (if/where applicable). Clearly allocated parking areas present. All parking spaces free of oil stains.	● Good	● Good	📷 3 photos

Car Parking Space Photos

Overview (Parking Space)



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	17.1.1



Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	17.1.2




Provided by	Inspector
Captured (Certified by inspector)	29/03/2026
Added	29/03/2026
Reference	17.1.3

18 Keys				
Item	Description	Condition	Cleanliness	Photos
18.1 General Overview	Immaculate. Clean & Tidy. Neutral smell/no odours evident. Professionally cleaned (0-1 months ago) Consistent with age. Neutral smell (no smoking or pet odours). 1 front door key provided to the tenants. 1 back door key provided to the tenants. 1 garage key provided to the tenants.	● Good	● Excellent	📷 2 photos



Keys Photos

General Overview



Provided by

Inspector

Captured (Certified by inspector)


29/03/2026

Added

30/03/2026

Reference

18.1.1



Provided by

Inspector

Captured (Certified by inspector)

29/03/2026

Added

30/03/2026

Reference

18.1.2

Page 44 of 49



Declaration

Was the tenant present during the inspection

NO

I hereby confirm approval of the accuracy and contents of the information contained within this report and my responses (if/where provided). I have also read, understood and agree to the disclaimer information contained within this report. I hereby confirm that the test function button of any smoke and carbon monoxide alarms (where present) in my property are/were in working order (alarm sounds when pressed) at the start of my tenancy. I also understand that it is my responsibility to ensure that any smoke or carbon monoxide alarms are tested and batteries replaced (where required) during my tenancy. Furthermore, in the event any such alarm becomes faulty, I will inform my landlord or managing agent with immediate effect to arrange a replacement.

Inspector Signature



Name:

Date:

30/03/2026 at 6:53pm

Tenant Signature

Hand-written signature required
(digital signature not provided).

Print name:

Date:

Disclaimer

The term 'Inspector' is used hereafter to define the Inventory Hive software user that is responsible for completing this property report. It is the duty and ultimate responsibility of the Inspector and Tenant to agree upon the accuracy of this report.

This report has been prepared by an inspector who is not an expert in buildings, furnishings, decorations, woods, antiques or a qualified surveyor.

This report relates only to the furniture and all the landlord's equipment and contents in the property. It is no guarantee, or report on, the adequacy of, or safety of, any such equipment or contents, merely a record that such items exist in the property at the date of preparing the report and the superficial condition of same.

The inspector will not take water readings unless the meter is clearly visible within the property or attached to an exterior wall at low accessible level.

Windows throughout the property have not been tested for function or operation. Descriptions are purely based on the superficial appearance of windows, frames and locks. The inspector can accept no liability arising from any failure of the windows or parts thereof to function properly at all.

Inspectors do not check gas or electrical appliances and give no guarantee with regard to the safety or reliability of such items. It should be noted that inspectors are not required to inspect smoke or carbon monoxide alarms, testing such alarm 'test functions' may occur. However, this is no guarantee, or report on, the adequacy of these alarms. It is merely a record that batteries were present (if tested) upon completion of this report.

The inspector cannot undertake to move heavy items of furniture or to make searches in inaccessible locations such as loft spaces, cellars, locked rooms and high level cupboards, or to unpack items. Inspectors reserve the right not to handle or move items deemed to be fragile or valuable. In addition, the inspectors reserve the right not to handle items that may be of a health hazard and to generalise/summarise on such items deemed to be unsuitable for further inspection.

Furniture and furnishings (Fire) Safety Regulations 1988 – (1993)

The fire and safety regulation regarding furnishings, gas, electrical and similar services are ultimately the responsibility of the instructing principle. Where the report notes "Fire Label Present", this should not be interpreted to mean the item complies with the "furniture and furnishings (fire) (safety) (amendments) 1993". It is a record that the item had a label as described or similar to that detailed in the "guide" published by the Department of Trade and Industry January 1997 (or subsequent date). It is not a statement that the item can be considered to comply with the regulations.

Safety Certificate and Legislation Compliance

The safety certificate and legislation compliance checklists in this report are no guarantee, or report on, the adequacy of, or safety of, any such liability contents, merely a record that such steps have been offered by the Inventory Hive software to highlight issues that may exist at the property at the date of preparing this report. Inventory Hive accepts no responsibility for the contents of these steps. It is the responsibility of the Inspector and Tenant to agree upon the accuracy of these steps.

Health & Safety / Insurance Risk-Avoidance Steps

The safety certificate and legislation compliance checklists in this report are no guarantee, or report on, the adequacy of, or safety of, any such liability contents, merely a record that such steps have been offered by the Inventory Hive software to highlight issues that may exist at the property at the date of preparing this report. Inventory Hive accepts no responsibility for the contents of these steps. It is the responsibility of the Inspector and Tenant to agree upon the accuracy of these steps.

Guidance Notes to Tenants

What should I know about the check-out process?

At the beginning of the tenancy it is important to note any specific discrepancies on the report that you do not agree with i.e marks on walls, carpets, etc. If no such additional notes are made via the electronic process at the start of the tenancy, the report will be deemed as accepted as read.

The condition of the property at the start of the tenancy, as described in the report will be compared to the condition of the property at the end of tenancy. Details of any alterations to the property after the report has been agreed upon will be recorded by an inspector (Inventory Hive user).

A 'Check-Out' report will be conducted to determine any changes to the report. The tenant should gain permission from the managing agent/landlord if they wish to remove or store any items during the tenancy and this should be confirmed in writing by the managing agent/landlord.

The inspector cannot undertake to move heavy items of furniture or to make searches in inaccessible locations such as loft spaces, cellars, locked rooms and high level cupboards, or to unpack items. Inspectors reserve the right not to handle or move items deemed to be fragile or valuable. In addition, the inspector reserves the right not to handle items that may be of a health hazard and to generalise/summarise on such items deemed to be unsuitable for further inspection.

What should I know before the check-out report is created?

All items should be returned to their original position (as detailed on the report); this includes stored or boxed items not used during the tenancy. Any items listed as 'Item Missing' can often result in a replacement cost or a charge being made. Managing agents/landlords may also charge for the removal of unapproved items left by a tenant at the end of the tenancy that were not included in the original report.

At the time of the property 'Check-Out' all personal items (including consumable items) should have been removed and cleaning of the property completed. Generally, no further cleaning is permitted once the 'Check-Out' inspection has commenced. Tenants should be advised of the date and time of the 'Check-Out' and provide access, or let the appointed inspector know the details of their departure of the property. Additional costs are sometimes charged by managing agents/landlords if the inspector is not able to complete the 'Check-Out' inspection due to the tenant not being ready to vacate or if they are delayed.

The 'Check-Out' report is advisory and is based on information available to the inspector at the time of the 'Check-Out'. It must not be treated as a final statement of tenant responsibility. It remains the responsibility of the agent/landlord and tenant to fully agree any issues and/or deductions (if any) from the deposit.

Issues to look out for during the tenancy...

Cleaning

Soiling is not considered to be 'Fair wear & Tear', (as defined by the House of Lords as 'reasonable use of the premises by the tenant and the ordinary operation of natural forces, i.e; the passage of time'). Generally speaking, tenants are liable for the property to be cleaned to the same standard as detailed in the report at the start of the tenancy.

Soft Furnishings

Excessive discolouring which cannot be attributed to sun bleaching and/or the passage of time, soiling or damage may result in repair or cleaning costs being charged to tenants. Discolouration due to smoke, staining, burns or tears to curtains may also incur costs.

Flooring

Hard floors require sweeping and mopping where necessary (in accordance with any specialist cleaning materials/advice provided by the managing agent/landlord). Tenants are often charged by the managing agent/landlord for repairs or replacement costs due to soiling, staining or damage such as cigarette or iron burns.

Decoration

As specified in the majority of tenancy agreements, tenants should gain signed, written permission (keep a copy) from the managing agent/landlord prior to putting nails, pins and other fixtures into walls and ceilings and should avoid the use of tac or tape. Additional marks/fittings are often noted at the 'Check-Out' and any damage or repair work required is often charged to tenants by managing agents/landlords.

Beds & Linen

Mattresses, divan bases, pillows, and duvets are often inspected for soiling where practically possible. Costs may be incurred by tenants for clearing, compensation or a percentage of the replacement charge by the managing agent/landlord in the event that any such items are soiled beyond that noted to the report. Beds should not be made up at the time of the 'Check-Out' inspection and any linen should be left clean, pressed and folded.

Kitchen Surfaces and Sinks

Kitchen surfaces and sinks are often inspected for knife cuts, cup marks, scorch and burn damage. Using appropriate items such as chopping boards and heat pads will help prevent damage.

Crockery, Chinaware, Kitchen Utensils

These items are often checked for soiling, chips and damage. If damage has occurred that is not considered as consistent with 'fair wear and tear', compensation or replacement costs may be incurred by the tenant.

Keys

All keys listed in the report should be kept safe and handed back at the 'Check-Out'. When keys get lost or are not returned to the managing agent, landlord or inspector, tenants are often charged for replacement keys or possibly for the changing of locks. Any additional keys cut during the tenancy should also be returned to the agent.

Gardens & Exterior Areas

Most tenancy agreements state that the tenant is responsible for the maintenance of gardens and exterior areas such as driveways unless agreed in writing otherwise. This includes the cutting of lawns, weeding and maintaining the garden, paths, driveways, flowerbeds etc according to the season. If the standard is found to be below the condition as detailed to the report, (with consideration given for a change in season) tenants are often charged for necessary work to bring the affected area back the required level.